



# Certificate of Calibration

VECTOR LX

Red Light Enforcement Camera

"I confirm that the VECTOR LX Red Light Enforcement System described below has been calibrated to the documented parameters as recorded below using measurement devices calibrated to National Standards in accordance with the Home Office Type Approval for the VECTOR LX device

All parts and components used in Device Serial Numbers NRLX0008A and NRLX0008B including any replaced are identical to those used in the device as Type-Approved"

Signed by:

A handwritten signature in blue ink, appearing to be "G Southwood".

Graeme Southwood  
**Technical Director**

Calibrating Engineer:

Steve Pigden & Ashley Morrison

RLSE Project ID

44

Camera Location

Ffairfach

Device Serial Numbers

NRLX0008A and NRLX0008B

Calibration Date:

06/06/2017

Valid Until:

05/06/2018



Location	
Site Name	Ffairfach
Site Code Reference	LXCRT0008

Primary Camera Calibration	
Column Identify	NRLX0008A
Column Location	South
Radar Serial Number	FTU200X-0520-14
Matrix Serial Number	7301-1G23
VECTOR Serial Number	SB441013-0153
Distance to Stop Line	18 m
Date of Stop Line Measurement	10/06/2016
Site Calibrated by	Steve Pigden & Ashley Morrison

Secondary Camera Calibration	
Column Identify	NRLX0008B
Column Location	North
Matrix Serial Number	7301-2H26
VECTOR Serial Number	SB441013-0155
Distance to Stop Line	17 m
Date of Stop Line Measurement	10/06/2016
Site Calibrated by	Steve Pigden & Ashley Morrison

Calibration Tools				
Road Wheel	Calibration Date:	12/08/2015	Serial Number:	543913