


# Certificate of Calibration

## Red Light Enforcement Camera

|   |                                 |
|---|---------------------------------|
| <b>Certificate of Calibration Number:</b> | RFCC-2017-0012                  |
| <b>Device:</b>                            | ROADflow Signal Metro           |
| <b>Device Serial Number(s):</b>           | RF-RLEE-000013 & RF-RLEE-000014 |

|                               |                  |
|-------------------------------|------------------|
| <b>Camera Location:</b>       | Darsham, Suffolk |
| <b>Calibration Date:</b>      | 30/08/17         |
| <b>Next Calibration Date:</b> | 29/08/19         |

|                             |   |                       |
|-----------------------------|---|-----------------------|
| <b>Calibrating Engineer</b> |   |                       |
| <b>Name:</b> Jason Swan     | <b>Signature:</b>  | <b>Date:</b> 07/09/17 |

Systems Engineering & Assessment Ltd hereby certifies that the ROADflow Signal/ROADflow Signal Metro listed above has been calibrated in compliance with the Home Office Type Approval for this device.

The Inspection Records raised during the course of this calibration have been checked and every precaution taken to ensure their accuracy.

All parts and components used in this device are subject to the Type Approval including any replaced

Every reasonable precaution has been taken to assure the safety of the equipment and personnel directly or indirectly associated with this calibration.

|                                  |  |                       |
|----------------------------------|--|-----------------------|
| <b>Certificate Authorised By</b> |  |                       |
| <b>Name:</b> Tamsin Chambers     | <b>Signature:</b>  | <b>Date:</b> 07/09/17 |

| Location                 |                  |
|--------------------------|------------------|
| Level Crossing Site Name | Darsham, Suffolk |

| Camera One Calibration             |                        |
|------------------------------------|------------------------|
| Camera Location                    | South West of Crossing |
| Network Rail Site Code             | NRLX0029B              |
| Distance to Stop Line              | 17.2 metres            |
| Pole to Centre Line Distance       | 8.6 metres             |
| Width of Stop Line                 | 3.9 metres             |
| Device Serial Number               | RF-RLEE-000013         |
| Enforcement Computer Serial Number | TSBG10005546           |
| Camera Control Box Serial Number   | SEA/AD11462            |
| ANPR Camera Serial Number          | K1003003               |
| Overview Camera Serial Number      | K1003067               |
| Wig Wag Camera Serial Number       | K1003313               |
| External Illuminator Serial Number | K1003010               |

| Camera Two Calibration             |                        |
|------------------------------------|------------------------|
| Camera Location                    | North East of Crossing |
| Network Rail Site Code             | NRLX0029A              |
| Distance to Stop Line              | 19.4 metres            |
| Pole to Centre Line Distance       | 8.0 metres             |
| Width of Stop Line                 | 3.7 metres             |
| Device Serial Number               | RF-RLEE-000014         |
| Enforcement Computer Serial Number | TSBG10005521           |
| Camera Control Box Serial Number   | SEA/AD11464            |
| ANPR Camera Serial Number          | K1003004               |
| Overview Camera Serial Number      | K1003062               |
| Wig Wag Camera Serial Number       | K1003019               |
| External Illuminator Serial Number | K1003009               |

**Systems Engineering & Assessment Ltd**

Head Office Address: SEA, Beckington Castle, 17 Castle Corner, Beckington, Frome, Somerset BA11 6TA United Kingdom

T: +44 1373 852000 F: +44 1373 831133 info@sea.co.uk www.sea.co.uk