



Certificate of Calibration

VECTOR LX

Red Light Enforcement Camera

"I confirm that the VECTOR LX Red Light Enforcement System described below has been calibrated to the documented parameters as recorded below using measurement devices calibrated to National Standards in accordance with the Home Office Type Approval for the VECTOR LX device

All parts and components used in Device Serial Numbers NRLX0013B and NRLX0013A including any replaced are identical to those used in the device as Type-Approved"

Signed by:

A handwritten signature in blue ink, appearing to be "G Southwood".

Graeme Southwood
Technical Director

Calibrating Engineer:

Steve Pigden & Wayne Creber

RLSE Project ID

45

Camera Location

Llangadog

Device Serial Numbers

NRLX0013B and NRLX0013A

Calibration Date:

07/06/2018

Valid Until:

06/06/2019



Location	
Site Name	Llangadog
Site Code Reference	LXCRT0013

Primary Camera Calibration	
Column Identify	NRLX0013B
Column Location	West
Radar Serial Number	FTU200X-0527-14
Matrix Serial Number	7301-1G25
VECTOR Serial Number	SB441013-0154
Distance to Stop Line	19 m
Date of Stop Line Measurement	09/06/2016
Site Calibrated by	Steve Pigden & Wayne Creber

Secondary Camera Calibration	
Column Identify	NRLX0013A
Column Location	East
Matrix Serial Number	7301-2H28
VECTOR Serial Number	SB440814-0618
Distance to Stop Line	15 m
Date of Stop Line Measurement	09/06/2016
Site Calibrated by	Steve Pigden & Wayne Creber

Calibration Tools				
Road Wheel	Calibration Date:	12/08/2015	Serial Number:	543913