



Certificate of Calibration

VECTOR LX

Red Light Enforcement Camera

"I confirm that the VECTOR LX Red Light Enforcement System described below has been calibrated to the documented parameters as recorded below using measurement devices calibrated to National Standards in accordance with the Home Office Type Approval for the VECTOR LX device

All parts and components used in Device Serial Numbers NRLX0007A and NRLX0007B
including any replaced are identical to those used in the device as Type-Approved"

Signed by:

A handwritten signature in black ink, appearing to read "R Fry".

Richard Fry
Operations Director

Calibrating Engineer:

Wayne Creber & Darryn Picknell

RLSE Project ID

122

Camera Location

Fairbourne

Device Serial Numbers

NRLX0007A and NRLX0007B

Calibration Date:

29/05/2019

Valid Until:

28/05/2020



Location	
Site Name	Fairbourne
Site Code Reference	LXCRT0007

Primary Camera Calibration	
Column Identify	NRLX0007A
Column Location	South West
Radar Serial Number	FTU200X-0413-13
Matrix Serial Number	7301-1E15
VECTOR Serial Number	SB441013-0192
Distance to Stop Line (m)	20
Date of Stop Line Measurement	02/06/2016
Site Calibrated by	Wayne Creber & Darryn Picknell

Secondary Camera Calibration	
Column Identify	NRLX0007B
Column Location	North East
Matrix Serial Nंबर	7301-2F19
VECTOR Serial Number	SB441013-0159
Distance to Stop Line (m)	15
Date of Stop Line Measurement	02/06/2016
Site Calibrated by	Wayne Creber & Darryn Picknell

Calibration Tools				
Road Wheel	Calibration Date:	12/08/2015	Serial Number:	543913